MARYLAND HISTORICAL TRUST	SURVEY NUMBER: AA 36/
21 STATE CIRCLE	NEGATIVE FILE NUMBER:
SHAW HOUSE ANNAPOLIS, MARYLAND 21401	
ANNAPOLIS, MARYLAND 21401	UTM REFERENCES:
HISTORIC SITES SURVEY FIELD SHEET	Zone/Easting/Northing
Individual Structure Survey Form	
individual belucedie baivey rorm	W 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	U.S.G.S. QUAD. MAP:
	PRESENT FORMAL NAME:
	I RESERT FORMAL NAME:
COUNTY: Anne Arundel	ORIGINAL FORMAL NAME:
TOWN: Annapolis	
LOCATION:	PRESENT USE: Single Family Residence
l Cathedral	ORIGINAL USE: " " "
	ARCHITECT/ENGINEER:
COMMON NAME:	
	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: Res Map 32 Par 106	DVINGTON COVIDED
OWNER: Kilborn Helen ADDRESS: 1 Cathedral St.	PHYSICAL CONDITION OF STRUCTURE:
Annapolis, MD 21401	Excellent (XX) Good ( ) Fair ( ) Poor: ( )
ACCESSIBILITY TO PUBLIC:	Fair() Poor:()   THEME:
Yes(x) No () Restricted()	
LEVEL OF SIGNIFICANCE:	STYLE: Victorian Mansard   DATE BUILT:
Local ( ) State ( ) National ( )	1885-1891
GENERAL DESCRIPTION:	
Structural System	
1. Foundation: Stone(X)Brick()Concrete()Concrete Block()	
2. Wall Structure	
A. Wood Frame: Post and Beam()Balloon(X)	
B. Wood Bearing Masonry: Brick()Stone()Concrete()Concrete Block()	
C. Iron() D. Steel() E. Other:  3. Wall Covering: Clapboard()Board and Batten()Wood Shingle()Shinler()	
3. Wall Covering: Clapboard()Board and Batten()Wood Shingle()Shiplap() Novelty(X)Stucco()Sheet Metal()Aluminum()Asphalt Shingle()	
Brick Veneer()Stone Veneer()Asbestos Shingle(X)	
Bonding Pattern:	Other:
4. Roof Structure	other.
A. Truss: Wood(X)Iron()Steel()Concrete()	
B. Other:	
5. Roof Covering: Slate()Wood Shingle(X)Asphalt Shingle(X)Sheet Metal()	
Built Up()Rolled()Tile()Other:	
6. Engineering Structure: 7. Other:	
7. Other: Appendages: Porches(X)Towers()Cupolas()Dormers(X)Chimneys(X)Sheds()Ells(X)	
Wings () Other:	
Roof Style: Gable()Hip()Shed()Flat()Mansard(X)Gambrel()Jerkinhead()	
Saw Tooth()With Monitor()With Bellcast()With Parapet()With False Front()	
Other:	
Number of Stories: 3	
Number of Bays: Entrance Location: Right	
Approximate Dimensions: 18x40	
•	
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat( )Zoning( )Roads( )	Positive()Negative()
Development()Deterioration()	Mixed() Other:
Alteration ( )Other:	

# 120% 1.11

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Pedimented dormers, good bracketed cornice at false Mansard front roof; molded window caps, transem lit door; full width porch with Tuscan columns; asbestos shingles at sides and rear; Mansard has scalloped shingles.

RELATED STRUCTURES: (Describe)

## STATEMENT OF SIGNIFICANCE:

Good example of Vernacular with false Mansard, contributes to streetscape at this important corner site.

## REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
Moderately Built Up()Densely-Built Up()
Residential()Commercial()

Agricultural()Industrial()
Roadside Strip Development()

Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983

1. STATE Annapolis, Maryland COUNTY

TOWN VICINITY
STREET NO. | Cathedral Street

ORIGINAL OWNER
ORIGINAL USE residence
PRESENT OWNER
PRESENT USE residence
WALL CONSTRUCTION clapboard
NO. OF STORIES three

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

2. NAME

DATE OR PERIOD C 1809 STYLE Victorian ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC MO

Second oldest house on this block after No. II. A fine example of a "Victorian house - a long thin house thatis mostly façade. Front is 2 storêys plus mansard on 3rd storey. Mansard is shingle (scalloped) painted to look like slate - there are 2 "dormers projecting; below mansard is fine modillion and bracket cornice. Ist and 2nd storey windows have shutters (louvred) - lst storey porch with columns - stone base - sidewalk cobbled. Possibly built by same person who did Nos. 97,99 Cathodral. A fine building by itself No I is important visually, it is on the corner and acts as a definite ending spot for "Federal" style houses on Cathodral.



good

5. PHYSICAL CONDITION OF STRUCTURE

6. LOCATION MAP (Plan Optional)

PUBLISHED SOURCES (Author, Title, Pages)
 INTERVIEWS, RECORDS, PHOTOS, ETC.


Leonard Michaels -No II Cathedral 7. PHOTOGRAPH

9. NAME, ADDRESS AND TITLE OF RECORDER

William D. Morgan Columbia University New York City

DATE OF RECORD June 23, 1967

9429





1 Cathedral

AA 361

Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,
Annapolis, Maryland
Www.Elevation/camera facing



AA-361

400

PHOTOGRAPH BY

1 Cathely 57 V 23/67, While